



SERVICE BULLETIN: 20090423

TAILGATE SERVICE BULLETIN

DAILY VISUAL INSPECTION

A daily visual inspection (truck walk-around) should be conducted to ensure the tailgate and its related component parts are in proper place, in proper working order, and that no damage or fatigue has affected critical areas such as bolts, nuts and other fastening areas.

Pay close attention to the Tailgate Pivot Pins, Pivot Pin Retainer Bolts, Chain and Chain Bolts. If a Pivot Pin Retainer Bolt is missing, the Autogate® Tailgate faces a risk of catastrophic damage, which may create a safety issue.

Most bolts, nuts and chain on PHIL Autogate® Tailgates are forged and made specifically for Philippi-Hagenbuch, Inc. to be longer lasting and stand up to the demands of mining environments. As such, they are not commercially available other than through Philippi-Hagenbuch, Inc. If you need replacement parts, obtain authentic PHIL replacement parts directly from Philippi-Hagenbuch, Inc. or through your off-highway truck dealer at:

(800) 447-6464

+1 (309) 697-9200

www.philsystems.com

sales@philsystems.com